

# VEHICLE INSPECTION REPORT

**LR62VBY**

## Fiat 500 1.2 Lounge 3dr Dualogic [Start Stop]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



### Details

Reg. date	31/12/2012	VIN	ZFA31200000922539	CAP Average	£3,200.00
Year	2012	Body Style	Hatchback	CAP Below	£2,650.00
Mileage	36,642 Miles Warranted	Keys	1	Gearbox	SEMI AUTO
Fuel Type	Petrol	MOT Due	30/08/2026	Gears	5
Colour	WHITE	CAP Clean	£3,750.00	Doors	3

### Tyres

NSF	MAXXIS	5.0mm
NSR	MAXXIS	5.0mm
OSF	MAXXIS	5.0mm
OSR	FULDA	5.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front head restraints
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- ABS
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- Drivers airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bumper Front  
Chipped  
1 To 5



2: Bonnet  
Chipped  
1 To 5





3: Wheel nsf  
Scratched  
Over 50mm



4: Door nsf  
Scratched  
Over 25mm Thru Paint



5: Wheel nsr  
Scratched  
Over 50mm




6: Qtr Panel nsr  
Dented  
With Paint Damage



7: Bumper Rear Moulding  
Scratched (Painted)  
Over 25mm Thru Paint



8: Qtr Panel osr  
Dented  
Between 10mm + 30mm



9: Door osf  
Dented  
Between 10mm + 30mm

10: Screen Front  
Chipped  
Over 10mm

## Interior

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK