



# VEHICLE INSPECTION REPORT

**AF66ONK**

## Ford Grand C-Max 1.5 TDCi Titanium 5dr Powershift

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	14/10/2016	Keys	2	CAP Clean	£5,175.00
Year	2016	Service history	Yes	CAP Average	£4,475.00
Mileage	61,977 Miles Warranted	Service documents	Service Book	CAP Below	£3,775.00
Fuel Type	Diesel	Number of stamps	6	Gearbox	AUTOMATIC
Colour	SILVER	Last service date	03/09/2024	Gears	6
VIN	WF0WXXGCEWGL77332	Last service miles	55,602		
Body Style	MPV	MOT Due	Expired		

£100 ADDITIONAL FEE. Last service 03/09/2024 at 55602 miles (6 main dealer services). 7 seater

### Tyres


NSF	FALKEN	4.0mm
NSR	FALKEN	4.0mm
OSF	FALKEN	4.0mm
OSR	FALKEN	4.0mm
Spare		

### Photos






## Condition Check



## Damage Photos




1: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



2: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



3: Boot Lid  
Scratched  
UpTo 25mm Thru Paint



4: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



5: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



6: Wheel osr  
Scratched  
Over 50mm



7: Door osr  
Chipped  
Multiple Chips




8: Door osf  
Chipped  
1 To 5

No Image



9: Door osf  
Scratched  
Over 25mm Not Thru Paint

10: Wheel osf  
Scratched  
Up To 50mm



11: Screen Front  
Chipped  
UpTo 10mm



12: Bonnet  
Chipped  
1 To 5



13: Bumper Front  
Chipped  
Multiple Chips

No Image

14: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



15: Wheel nsf  
Scratched  
Up To 50mm

No Image

16: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



17: Door nsf  
Dented  
Over 2 UpTo 10mm

No Image

18: Door nsf  
Scratched  
Over 25mm Not Thru Paint




19: Door nsr  
Poor Previous Repair  
Poor Paint



20: Wheel nsr  
Scratched  
Over 50mm



21: Qtr Panel nsr  
Chipped  
1 To 5



22: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint

**Interior**

**Carpet Condition**                    -  
**Seat Condition**                    -

**Upholstery Condition**           -  
**Odour**                                   -