



46 Brampton Road
Eastbourne
BN229BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GU14KJE

Volkswagen Tiguan 2.0 TDi BlueMotion Tech Match 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	11/03/2014	Keys	2	CAP Clean	£4,625.00
Year	2014	Service history	Yes	CAP Average	£4,025.00
Mileage	92,063 Miles Warranted	Service documents	Service Book	CAP Below	£3,400.00
Fuel Type	Diesel	Number of stamps	10	Gearbox	MANUAL
Colour	BLACK	Last service date	12/02/2024	Gears	6
VIN	WVGZZZ5NZEW087587	Last service miles	87,313		
Body Style	Estate	MOT Due	08/03/2026		

Last Service: 12/02/2024 at 87313 miles. (10 services (3 main dealer))

Tyres

NSF	DUNLOP	6.0mm
NSR	DUNLOP	6.0mm
OSF	DUNLOP	6.0mm
OSR	DUNLOP	5.0mm
Spare	BUDGET	OK

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- PAS
- Radio/CD
- Climate control
- Rear headrests
- ESP
- Remote central locking

Photos






Condition Check



Damage Photos



1: Wing osf
Dented
2 Or Less UpTo 10mm



2: Door osf
Dented
2 Or Less UpTo 10mm



3: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



4: Wheel osr
Scratched
Up To 50mm



5: Bumper Rear
Chipped
1 To 5




6: Wheel nsf
Scratched
Over 50mm



7: Bumper Front
Scratched
25 to 100mm Thru Paint



8: Bumper Front
Scratched
Over 25mm Not Thru Paint



9: Bonnet
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK