

# VEHICLE INSPECTION REPORT

**RK16XKX**

## Ford Fiesta 1.0 EcoBoost 140 Zetec S Red 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	11/03/2016	Keys	2	CAP Clean	£3,100.00
Year	2016	Service history	Yes	CAP Average	£2,650.00
Mileage	75,510 Miles Warranted	Service documents	Service Book	CAP Below	£2,175.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	MANUAL
Colour	RED	Last service date	17/11/2023	Gears	5
VIN	WF0CXXGAKCGR51047	Last service miles	55,527	Doors	3
Body Style	Hatchback	MOT Due	16/11/2025		

Last Service: 17/11/2023 at 55527 miles. (7 services (2 main dealer) ) Tyre pressure light on

### Tyres

NSF	LAUFENN	3.0mm
NSR	LAUFENN	6.0mm
OSF	LAUFENN	5.0mm
OSR	LAUFENN	6.0mm
Spare	BUDGET	OK

## Features


- Bluetooth connection
- Radio/CD
- Front armrest
- ABS
- Traction control
- Cloth seat trim
- PAS
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear headrests
- ESP
- Central locking
- Telephone
- Air conditioning
- Solid Paint
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Door osf  
Dented  
With Paint Damage



2: Door Mirror Assy osf  
Scratched (Painted)  
UpTo 25mm Thru Paint





3: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



4: Qtr Panel nsr  
Dented  
2 Or Less Up To 10mm



5: Wing nsf  
Dented  
Between 10mm + 30mm



6: Bonnet  
Chipped  
1 To 5



7: Wheel osf  
Scratched  
Up To 50mm



8: Wheel osr  
Scratched  
Up To 50mm



9: Wheel nsr  
Scratched  
Over 50mm

10: Wheel nsf  
Scratched  
Over 50mm

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK