



46 Brampton Road
Eastbourne
BN22 9BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LX65KZO

Ford Kuga 2.0 TDCi 180 Titanium X Sport 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	27/09/2015	VIN	WF0AXXWPMFT37806	CAP Average	£7,800.00
Year	2015	Body Style	Hatchback	CAP Below	£6,775.00
Mileage	22,473 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	20/05/2026	Gears	6
Colour	WHITE	CAP Clean	£8,800.00	Doors	5

£100 ADDITIONAL FEE

Tyres

NSF	MICHELIN	6.0mm
NSR	MICHELIN	6.0mm
OSF	MICHELIN	6.0mm
OSR	MICHELIN	6.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Leather seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable drivers seat
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- PAS
- Radio/CD
- Opening panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Poor Previous Repair
Rippled UpTo 30%



5: Door nsr
Poor Previous Repair
Poor Paint



6: Wheel nsr
Scratched
Over 50mm



7: Wheel osr
Scratched
Over 50mm



8: Door osr
Poor Previous Repair
Rippled UpTo 30%



9: Door nsf
Poor Previous Repair
Rippled Over 30%



10: Wheel osf
Scratched
Over 50mm



11: Roof
Chipped
Over 5mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK