



VEHICLE INSPECTION REPORT

GF11ZRZ

Vauxhall Corsa 1.2 Excite 3dr [AC]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	26/07/2011	VIN	W0L0SDL08B6116585	Gearbox	MANUAL
Year	2011	Body Style	Hatchback	Gears	5
Mileage	39,769 Miles Warranted	Keys	2	Doors	3
Fuel Type	Petrol	Service history	None		
Colour	RED	MOT Due	Expired		

NO SERVICE HISTORY. EXPIRED MOT. Eml light is on
Abs light is on
Rattling engine

Tyres

NSF	CONTINENTAL	2.0mm
NSR	CONTINENTAL	2.0mm
OSF	CONTINENTAL	2.0mm
OSR	CONTINENTAL	2.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Folding rear seats
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Body coloured bumpers
- Front electric windows
- Solid Paint
- ESP
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Cloth seat trim
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- ABS
- Passenger airbag
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
UpTo 25mm Thru Paint



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Dented
With Paint Damage




10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Tailgate Trim Panel
Broken
Replace



12: Wheel osr
Scratched
Over 50mm



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Door osf
Chipped
Edge Chip



15: Wheel osf
Scratched
Over 50mm



16: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	Fault		
Windows	OK	Radio	OK
		Steering	OK