



VEHICLE INSPECTION REPORT

GN18UWF

Ford Fiesta 1.0 EcoBoost 125 Titanium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	08/03/2018	Service history	Yes	CAP Average	£4,975.00
Year	2018	Service documents	Service Book	CAP Below	£4,200.00
Mileage	69,878 Miles Warranted	Number of stamps	7	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	21/03/2025	Gears	6
Colour	GREY	Last service miles	68,815	Doors	5
VIN	WF0JXXGAHJL56184	MOT Due	06/02/2026		
Body Style	Hatchback	CAP Clean	£5,775.00		

£65 ADDITIONAL FEE Last service 21/03/2025 @ 68815 miles (7 MAIN DEALER SERVICES)

Tyres


NSF	NEXEN	4.0mm
NSR	TOYO	3.0mm
OSF	NEXEN	4.0mm
OSR	TOYO	2.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- ABS
- Traction control
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Body coloured bumpers
- Climate control
- Rear headrests
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- PAS
- Trip computer
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Rear parking sensor
- Audio remote control
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Screen Front
Chipped
UpTo 10mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Chipped
1 To 5



7: Door nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Up To 50mm



9: Bumper Rear
Chipped
Multiple Chips



10: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



11: Wheel osr
Scratched
Over 50mm



12: Door osr
Scratched
Over 25mm Not Thru Paint



13: Door osf
Chipped
1 To 5



14: Wing osf
Chipped
1 To 5



15: Wheel osf
Scratched
Over 50mm



16: Door Pad osf
Broken
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK