

VEHICLE INSPECTION REPORT

SL60HZX

Renault Wind 1.6 VVT Dynamique S 2dr

inspection		venicie			nama
Serious Damage?	No	VAT	Margin		Grape Grape
		V5	TBC		
Details					
Reg. date	31/10/2010	VIN	VF1EN0R0544076154	CAP Average	£880.00
Year	2010	Body Style	Convertible	CAP Below	£475.00
Mileage	60,922 Miles Warranted	Keys	2	Gearbox	MANUAL
		MOT Due	27/03/2026	Gears	5
Fuel Type	Petrol	CAP Clean	£1,275.00	•	
Colour	BLUE		·		

£65 ADDITIONAL FEE.

Гу	r	е	S

,			
NSF	NANKANG	4.0mm	
NSR	NANKANG	4.0mm	
OSF	NANKANG	4.0mm	
OSR	NANKANG	4.0mm	
Spare			

Features

- Cruise control
 Body coloured bumpers
 Front electric windows
 Passenger airbag
 Alloy wheels

- Steering wheel mounted controls Audio remote control
- Electric door mirrorsMetallic PaintCentral locking

- Air conditioningABS
- Remote central locking
- Radio/CD
- Climate control
- Drivers airbag Leather seat trim

Photos





















Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Bumper Front Chipped Multiple Chips

No Image

3: Bumper Front Scratched Over 25mm Not Thru Paint



4: Wheel nsf Scratched Over 50mm

No Image

5: Wing nsf Scratched Over 25mm Not Thru Paint



6: Door nsf Dented With Paint Damage



7: Qtr Panel nsr Dented Over 2 UpTo 10mm

No Image

8: Qtr Panel nsr Scratched Over 25mm Not Thru Paint



9: Wheel nsr Scratched Over 50mm



10: Bumper Rear Scratched 25 to 100mm Thru Paint

No Image

11: Bumper Rear Scratched Over 25mm Not Thru Paint



12: Boot Lid Chipped 1 To 5

No Image






14: Qtr Panel osr Chipped 1 To 5

No Image

15: Qtr Panel osrScratchedOver 25mm Not Thru Paint



17: Door osf Poor Previous Repair Poor Paint



19: Wheel osf Scratched Over 50mm



16: Wheel osr Scratched Over 50mm



18: Wing osf Chipped 1 To 5



20: Seat Back Cover osf Scuffed Over 25mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake O		Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK