



## VEHICLE INSPECTION REPORT

**PO64YCV**

### Fiat 500 1.2 Pop 3dr [Start Stop]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama  
GRADE  
**2**

#### Details

Reg. date	02/09/2014	VIN	ZFA3120000J221184	CAP Average	£1,500.00
Year	2014	Body Style	Hatchback	CAP Below	£1,075.00
Mileage	74,252 Miles Warranted	Keys	1	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	03/04/2026	Gears	5
Colour	WHITE	CAP Clean	£1,900.00	Doors	3

£100 ADDITIONAL FEE

Tyres		
NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	HIFLY	5.0mm
Spare	BUDGET	OK

### Features


- PAS
- Electric door mirrors
- Drivers airbag
- Steel wheels
- Rear wiper
- Front electric windows
- Central locking
- Radio/CD
- Solid Paint
- Remote central locking
- Body coloured bumpers
- ABS
- Cloth seat trim

### Photos





## Condition Check



## Damage Photos



1: Other  
N/A  
N/A



2: Wing of  
Dented  
Between 10mm + 30mm





3: Sill os  
Scratched  
Over 25mm Not Thru Paint



4: Door osf  
Chipped  
Edge Chip



5: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



6: Bumper Front  
Scratched  
25 to 100mm Thru Paint



7: Bonnet  
Chipped  
Multiple Chips



8: A Post os  
Chipped  
1 To 5

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK