

VEHICLE INSPECTION REPORT

GU20NKD

Hyundai Kona 1.0T GDi Play Edition 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		Grape 3
		V5	Present		
Details					
Reg. date	06/03/2020	Keys	2	CAP Clean	£8,800.00
Year	2020	Service history	Yes	CAP Average	£7,775.00
Mileage	39,957 Miles Warranted	Service documents	Service Book	CAP Below	£6,725.00
		Number of stamps	3	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	19/09/2023	Gears	6
Colour	RED	Last service miles	25,621	Doors	 5
VIN	KMHK2811LLU378871	MOT Due	05/03/2026		
Body Style	Hatchback		33, 33, 2320		

£65 ADDITIONAL FEE. Last Service: 19/9/2023 at 25621 miles. (3 services 2 main dealer). Book & print.

Tyres	3
-------	---

NSF	YOKOHAMA	6.0mm
NSR	HANKOOK	3.0mm
OSF	YOKOHAMA	4.0mm
OSR	HANKOOK	4.0mm
Spare	BUDGET	OK

Features

- Bluetooth connection
- Rear wiperElectric door mirrors
- Rear electric windows
 Drivers airbag
 Tyre pressure monitor
 Alloy wheels

- Cruise control
- Telephone
- Air conditioning
- Rear headrestsESP
- Central locking
- · Park assist camera
- Radio/CD
- Front armrest
- Metallic Paint
- Passenger airbagRemote central locking

- Body coloured bumpers Front electric windows
- ABS
 Traction control
- · Cloth seat trim

Photos












Condition Check



Damage Photos



1: Door osf Chipped 1 To 5



2: Door osf Chipped Edge Chip



3: Door osr Chipped 1 To 5



4: Qtr Panel osr Chipped 1 To 5




5: Door nsf Scratched Over 25mm Thru Paint



6: Wing nsf Dented With Paint Damage



7: Roof Chipped 1 To 5



8: Wheel osf Scratched Over 50mm



9: Wheel osr Scratched Over 50mm



10: Wheel nsr Scratched Over 50mm



11: Wheel nsf Scratched Over 50mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK