



# VEHICLE INSPECTION REPORT

**BK56EWL**

## BMW X5 3.0d Sport 5dr Auto

| Inspection      |    | Vehicle |         |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT     | Margin  |
|                 |    | V5      | Present |



### Details

|           |                            |                   |            |                    |            |
|-----------|----------------------------|-------------------|------------|--------------------|------------|
| Reg. date | 29/09/2006                 | Body Style        | Estate     | Last service miles | 100,511    |
| Year      | 2006                       | Keys              | 1          | MOT Due            | 17/11/2025 |
| Mileage   | 166,837 Miles<br>Warranted | Service history   | Yes        | Gearbox            | AUTOMATIC  |
| Fuel Type | Diesel                     | Service documents | Printout   | Gears              | 6          |
| Colour    | GREY                       | Number of stamps  | 2          |                    |            |
| VIN       | WBAFB72060LX27763          | Last service date | 07/09/2016 |                    |            |

LAST SERVICE 7/9/16 @ 100,511 MILES (2 MAIN DEALER) PRINT Slight tapping

### Tyres

|       |        |       |
|-------|--------|-------|
| NSF   | BUDGET | 4.0mm |
| NSR   | BUDGET | 4.0mm |
| OSF   | BUDGET | 3.0mm |
| OSR   | BUDGET | 4.0mm |
| Spare |        |       |

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Remote central locking
- Cruise control
- Audio remote control
- Air conditioning
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Leather seat trim
- PAS
- Digital radio
- Climate control
- Front electric windows
- Rear electric windows
- ABS
- Passenger airbag
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Rear headrests
- Curtain airbags
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Dented  
Over 30mm



2: Bumper Front  
Poor Previous Repair  
Rippled Up To 30%





3: Wing nsf  
Poor Previous Repair  
Poor Paint




4: Wheel nsf  
Scratched  
Over 50mm



5: Door Mirror Assy nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint



6: Door nsf  
Dented  
Over 2 UpTo 10mm



7: Door nsf  
Scratched  
Over 25mm Not Thru Paint



8: Door nsr  
Dented  
Over 30mm



9: Wheel nsr  
Scratched  
Over 50mm



10: Qtr Panel nsr  
Poor Previous Repair  
Poor Paint



11: Bumper Rear  
Dented  
With Paint Damage



12: Boot Lid  
Chipped  
1 To 5



13: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



14: Wheel osr  
Scratched  
Over 50mm





15: Door osr  
Poor Previous Repair  
Poor Paint



16: Door osf  
Poor Previous Repair  
Poor Paint



17: Wing osf  
Chipped  
1 To 5



18: Wheel osf  
Scratched  
Over 50mm



19: Screen Front  
Chipped  
UpTo 10mm



20: Door Lock osf  
Broken  
Replace

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|                          |    |                                                |    |
|--------------------------|----|------------------------------------------------|----|
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Turbo Boosting           | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake            | OK | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | DPF light illuminated                          | OK |
| ABS light illuminated    | OK | Service indicator light illuminated            | OK |
| Windows                  | OK | Radio                                          | OK |
|                          |    | Steering                                       | OK |