



VEHICLE INSPECTION REPORT

GL60VYO

Audi TT 1.8T FSI 2dr [2011]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	29/01/2011	VIN	TRUZZZ8J7B1008534	CAP Average	£2,550.00
Year	2011	Body Style	Convertible	CAP Below	£2,050.00
Mileage	86,518 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	10/11/2025	Gears	6
Colour	GREY	CAP Clean	£3,025.00		

£65 ADDITIONAL FEE

Tyres


NSF	MAXXIS	6.0mm
NSR	MAXXIS	6.0mm
OSF	MAXXIS	6.0mm
OSR	MAXXIS	6.0mm
Spare		

Features


- Cruise control
- Trip computer
- Electric door mirrors
- Front electric windows
- Steering wheel reach adjustment
- Passenger airbag
- Leather seat trim
- PAS
- Audio remote control
- Front fog lights
- Front head restraints
- Metallic Paint
- Traction control
- Partial leather seat trim
- Rear parking sensor
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- ABS
- Central locking
- Alloy wheels
- Steering wheel mounted controls
- Body coloured bumpers
- Climate control
- Steering wheel rake adjustment
- Drivers airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bumper Rear
Chipped
Multiple Chips



2: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



3: Wheel nsr
Scratched
Up To 50mm

No Image

4: Door nsf
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Scratched
Up To 50mm



6: Bumper Front
Chipped
Multiple Chips




7: Bonnet
Chipped
1 To 5




8: Wheel osf
Scratched
Up To 50mm



9: Wheel osr
Scratched
Over 50mm



10: Door osf
Scratched
Over 25mm Not Thru Paint



11: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK