



VEHICLE INSPECTION REPORT

YH57YSC

BMW Z4 2.0i Sport 2dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	26/09/2007	Keys	3	CAP Clean	£1,475.00
Year	2007	Service history	Yes	CAP Average	£1,100.00
Mileage	92,700 Miles Warranted	Service documents	Service Book	CAP Below	£675.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	MANUAL
Colour	BLUE	Last service date	19/03/2024	Gears	6
VIN	WBABZ12090LZ66277	Last service miles	90,445		
Body Style	Convertible	MOT Due	22/03/2026		

£100 ADDITIONAL FEE Last service 19/03/2024 @90445 miles (8 SERVICES) book & print High Clutch

Tyres

NSF	GOODYEAR	5.0mm
NSR	BRIDGESTONE	6.0mm
OSF	GOODYEAR	6.0mm
OSR	BRIDGESTONE	6.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Air conditioning
- ABS
- Traction control
- Leather seat trim
- Heated front seat
- Body coloured bumpers
- Climate control
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ESP
- Central locking
- Telephone
- Electric sunroof
- Metallic Paint
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1:



2: Seat Back Cover osf
Scuffed
Over 25mm



3: Wing osf
Chipped
1 To 5




4: Door osf
Chipped
Edge Chip



5: Qtr Panel nsf
Scratched
Over 25mm Not Thru Paint



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Wing nsf
Chipped
1 To 5



8: Bumper Front
Chipped
Multiple Chips



9: Bonnet
Chipped
1 To 5



10: Screen Front
Chipped
UpTo 10mm



11: Bumper Front
Scratched
25 to 100mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK