



VEHICLE INSPECTION REPORT

GY65HSO

Citroen C4 1.6 BlueHDi [120] Flair 5dr EAT6

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	30/10/2015	Keys	2	CAP Clean	£3,875.00
Year	2015	Service history	Yes	CAP Average	£3,300.00
Mileage	28,788 Miles Warranted	Service documents	Service Book	CAP Below	£2,725.00
Fuel Type	Diesel	Number of stamps	11	Gearbox	AUTOMATIC
Colour	GREY	Last service date	24/01/2025	Gears	6
VIN	VF7NCBHZTFY561760	Last service miles	28,392	Doors	5
Body Style	Hatchback	MOT Due	19/09/2025		

Last Service - 24.01.2025 at 28392 miles (11 services 9 main dealer services)
Front suspension knock

Tyres

NSF	LAUFENN	5.0mm
NSR	LAUFENN	5.0mm
OSF	LAUFENN	5.0mm
OSR	LAUFENN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Drivers airbag
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Isofix child seat anchor points
- Cloth seat trim
- PAS
- Telephone
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Rear parking sensor
- Trip computer
- Climate control
- Height adjustable drivers seat
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint



2: Bonnet
Chipped
1 To 5



3: Wheel osf
Scratched
Over 50mm



4: Screen Front
Chipped
UpTo 10mm



5: Door osf
Chipped
1 To 5



6: Qtr Panel osr
Chipped
1 To 5



7: Wheel osr
Scratched
Over 50mm



8: Bumper Rear
Chipped
1 To 5



9: Boot Lid
Chipped
1 To 5



10: Qtr Panel nsr
Chipped
Multiple Chips



11: Wheel nsr
Scratched
Over 50mm



12: Door nsr
Chipped
1 To 5



13: Door nsf
Scratched
Up To 25mm Not Thru Paint



14: Wing nsf
Scratched
Over 25mm Thru Paint



15: Wheel nsf
 Scratched
 Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK