



# VEHICLE INSPECTION REPORT

**HV69OBR**

## Toyota Aygo 1.0 VVT-i X-Trend 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	30/09/2019	Keys	2	CAP Clean	£6,825.00
Year	2019	Service history	Yes	CAP Average	£5,975.00
Mileage	47,976 Miles Warranted	Service documents	Printout	CAP Below	£5,100.00
Fuel Type	Petrol	Number of stamps	5	Gearbox	MANUAL
Colour	RED	Last service date	27/08/2024	Gears	5
VIN	JTDKGNEC50N479295	Last service miles	40,074	Doors	5
Body Style	Hatchback	MOT Due	15/05/2025		

Last Service - 27.08.2024 at 40074 miles (5 main dealer services)

### Tyres

NSF	HIFLY	3.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare	BUDGET	

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear headrests
- ESP
- Central locking
- Cruise control
- Telephone
- Air conditioning
- Solid Paint
- Passenger airbag
- Remote central locking
- Park assist camera
- Radio/Cassette
- Climate control
- ABS
- Traction control
- Cloth seat trim
- PAS
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bumper Rear  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
1 To 5





3: Bonnet  
Chipped  
1 To 5



4: Wheel nsf  
Scratched  
Over 50mm



5: Wheel nsr  
Scratched  
Up To 50mm



6: Wheel osr  
Scratched  
Up To 50mm

**Interior**

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

**Vehicle Inspection Report**

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK