



VEHICLE INSPECTION REPORT

LJ10LLG

BMW 1 Series 118d Sport 2dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	19/05/2010	VIN	WBAUR12040VM18894	CAP Average	£1,275.00
Year	2010	Body Style	Coupe	CAP Below	£850.00
Mileage	98,750 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	26/09/2025	Gears	6
Colour	GREY	CAP Clean	£1,700.00		

Noisy engine

Tyres


NSF	RAPID	4.0mm
NSR	PIRELLI	3.0mm
OSF	RAPID	4.0mm
OSR	SUNNY	4.0mm
Spare		

Features


- Cruise control
- Audio remote control
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Insurance telematics
- Remote central locking
- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Steering wheel mounted controls
- Body coloured bumpers
- Climate control
- Rear headrests
- ABS
- Traction control
- Partial leather seat trim
- Trip computer
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- Drivers airbag
- Central locking
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Wing osf
Scratched
Over 25mm Not Thru Paint

4: Wheel osf
Scratched
Over 50mm

No Image



5: Door osf
Scratched
Over 25mm Not Thru Paint

6: Qtr Panel osr
Dented
Over 30mm



7: Wheel osf
Scratched
Over 50mm



8: Bumper Rear
Chipped
Multiple Chips

No Image

No Image

9: Boot Lid
Scratched
Over 25mm Not Thru Paint

10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



No Image

11: Wheel nsr
Scratched
Over 50mm

12: Door nsf
Scratched
Over 25mm Not Thru Paint



13: Wheel nsf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK