



# VEHICLE INSPECTION REPORT

**PJ58CXP**

## Volkswagen Golf GT TDI 140

| Inspection      |    | Vehicle |         |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT     | Margin  |
|                 |    | V5      | Present |

nama  
GRADE  
**5**

### Details

|           |                            |                   |              |                    |         |
|-----------|----------------------------|-------------------|--------------|--------------------|---------|
| Reg. date | 17/12/2008                 | Body Style        | Hatchback    | Last service miles | 121,643 |
| Year      | 2008                       | Keys              | 1            | MOT Due            | Expired |
| Mileage   | 121,643 Miles<br>Warranted | Service history   | Yes          | Gearbox            | MANUAL  |
| Fuel Type | Diesel                     | Service documents | Service Book | Gears              | 6       |
| Colour    | BLACK                      | Number of stamps  | 13           | Doors              | 5       |
| VIN       | WVVZZZ1KZ9W032768          | Last service date | 05/09/2023   |                    |         |

MOT EXPIRED.

Last service 05/09/2023 at 121,643 miles- 13 services (3 main dealer) Roof lining dropped

### Tyres

|       |          |       |
|-------|----------|-------|
| NSF   | MAXXIS   | 5.0mm |
| NSR   | GOODRIDE | 5.0mm |
| OSF   | MAXXIS   | 5.0mm |
| OSR   | BUDGET   | 5.0mm |
| Spare |          |       |

## Features


- Heated front seat
- Electric door mirrors
- Front electric windows
- ABS
- Central locking
- Rear wiper
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Leather seat trim
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Bumper Front  
Insecure  
Action Required



4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Chipped  
Multiple Chips



6: Screen Front  
Chipped  
Over 10mm



7: Sill ns  
Rusted  
Holed



8: Door nsf  
Dented  
With Paint Damage





9: Wheel nsr  
Scratched  
Over 50mm



10: Qtr Panel nsr  
Rusted  
Over 5mm



11: Bumper Rear  
Scratched  
Over 100mm Thru Paint



12: Wheel osr  
Scratched  
Over 50mm



13: Qtr Panel osr  
Dented  
With Paint Damage



14: Door osr  
Dented  
With Paint Damage





15: Door osf  
Dented  
Over 30mm



16: Flasher Side Repeater os  
Broken  
Replace



17: Wheel osf  
Scratched  
Over 50mm



18: Sill os  
Rusted  
Over 5mm



19: Roof  
Chipped  
Edge Chip

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|                          |    |                                                |    |
|--------------------------|----|------------------------------------------------|----|
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Turbo Boosting           | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake            | OK | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | DPF light illuminated                          | OK |
| ABS light illuminated    | OK | Service indicator light illuminated            | OK |
| Windows                  | OK | Radio                                          | OK |
|                          |    | Steering                                       | OK |