



# VEHICLE INSPECTION REPORT

**GH17CEA**

## Mercedes-Benz GLA GLA 220d 4Matic AMG Line 5dr Auto [Prem Plus]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	06/04/2017	Body Style	Estate	Last service miles	58,240
Year	2017	Keys	2	MOT Due	06/12/2025
Mileage	67,152 Miles Warranted	Service history	Yes	CAP Clean	£10,600.00
Fuel Type	Diesel	Service documents	Printout	CAP Average	£9,475.00
Colour	RED	Number of stamps	7	CAP Below	£8,325.00
VIN	WDC1569052J365648	Last service date	03/06/2024		

Last Service - 3.06.2024 at 58240 miles (7 main dealer services)

### Tyres

NSF	CONTINENTAL	4.0mm
NSR	CONTINENTAL	4.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Audio remote control
- Body coloured bumpers
- Opening panoramic glass roof
- Climate control
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Auxiliary input socket
- Electric door mirrors
- Roof rails
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Front parking sensor
- PAS
- Telephone
- Radio/CD
- Electric sunroof
- Xenon headlights
- Electrically adjustable passenger seat
- Rear armrest
- Steering wheel reach adjustment
- Curtain airbags
- Traction control
- Partial leather seat trim
- Heated front seat
- Rear parking sensor
- Trip computer
- USB/iPod interface
- Front fog lights
- Air conditioning
- Front armrest
- Rear electric windows
- Solid Paint
- Drivers airbag
- Central locking
- Alloy wheels

## Photos






## Condition Check



## Damage Photos



1: Bumper Front  
Poor Previous Repair  
Paint Flake



2: Bonnet  
Chipped  
1 To 5







3: Wing osf  
Chipped  
1 To 5




4: Wheel osf  
Scratched  
Over 50mm



5: Door osf  
Scratched  
Over 25mm Not Thru Paint



6: Door osr  
Chipped  
1 To 5



7: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



8: Bumper Rear  
Chipped  
1 To 5

No Image

9: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

No Image

10: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



11: Wheel nsr  
Scratched  
Over 50mm



12: Wheel osr  
Scratched  
Over 50mm

No Image

13: Door nsr  
Scratched  
Over 25mm Not Thru Paint

No Image

14: Door nsf  
Scratched  
Over 25mm Not Thru Paint



15: Wing nsf  
Chipped  
1 To 5



16: Wheel nsf  
Scratched  
Over 50mm

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** -

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		