



# VEHICLE INSPECTION REPORT

**GU16CJV**

## Ford Focus 1.6 125 Titanium 5dr Powershift

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	11/05/2016	Body Style	Hatchback	Last service miles	37,794
Year	2016	Keys	2	MOT Due	Expired
Mileage	47,363 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	3	Doors	5
VIN	WF05XXGCC5GR45421	Last service date	27/04/2023		

£100 ADDITIONAL FEE Last service 27/04/2023 @ 37794 miles (3 MAIN DEALER SERVICES) Vibration at idle

### Tyres

NSF	BUDGET	Worn
NSR	HIFLY	4.0mm
OSF	BUDGET	Worn
OSR	GT RADIAL	OK
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Reverse parking aid
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Audio remote control
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bumper Rear  
Chipped  
Multiple Chips



2: Qtr Panel nsr  
Dented  
Over 2 UpTo 10mm





3: Wheel nsr  
Scratched  
Over 50mm



4: Door nsr  
Chipped  
1 To 5



5: Wing nsf  
Chipped  
1 To 5



6: Wheel nsf  
Scratched  
Over 50mm



7: Screen Front  
Chipped  
UpTo 10mm



8: Bonnet  
Chipped  
1 To 5



9: Bumper Front  
Scratched  
25 to 100mm Thru Paint



10: Wing osf  
Chipped  
1 To 5




11: Wheel osf  
Scratched  
Over 50mm



12: Door osf  
Chipped  
1 To 5



13: Wheel osr  
Scratched  
Up To 50mm



14: Tyre nsf  
Worn  
Replace

No Image

15: Tyre osf  
Worn  
Replace

### Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK