



VEHICLE INSPECTION REPORT

EJ69FUB

Hyundai Kona 1.0T GDi Blue Drive Premium SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	17/12/2019	Body Style	Hatchback	Last service miles	72,439
Year	2019	Keys	2	MOT Due	24/05/2026
Mileage	77,243 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	6	Doors	5
VIN	KMHK3811LKU328373	Last service date	17/06/2025		

Last Service - 17.06.2025 at 72439 miles (6 services)

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	6.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Telephone
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Navigation system
- Radio/CD
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Door nsf
Dented
Between 10mm + 30mm



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



11: Tailgate
Dented
Between 10mm + 30mm



12: Wheel osr
Scratched
Up To 50mm



13: Qtr Panel osr
Dented
Between 10mm + 30mm



14: Door osr
Dented
Over 30mm



15: Door osf
Chipped
Edge Chip



16: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK