



VEHICLE INSPECTION REPORT

DA08NAE

Volvo C70 2.0D SE 2dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date 28/06/2008

Year 2008

Mileage 112,601 Miles
Warranted

Fuel Type Diesel

Colour BLACK

VIN YV1MC75519J070427

Body Style Convertible

Keys 1

MOT Due 06/06/2025

CAP Clean £820.00

CAP Average £540.00

CAP Below £275.00

Gearbox MANUAL

Gears 6

Smoking badly and both bumpers misaligned

Boot wont open

Dash screen faint and bulb light on

Tyres

NSF SUNNY 4.0mm

NSR RAPID 5.0mm

OSF MICHELIN 4.0mm

OSR RAPID 5.0mm

Spare

Features


- Bluetooth connection
- Steering wheel mounted controls
- Body coloured bumpers
- Climate control
- Rear electric windows
- Drivers airbag
- Remote central locking
- Cruise control
- Trip computer
- Electric door mirrors
- Electrically adjustable drivers seat
- Solid Paint
- Isofix child seat anchor points
- Leather seat trim
- Heated front seat
- Auxiliary input socket
- Front fog lights
- Front armrest
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- PAS
- Radio/CD
- Air conditioning
- Front electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wing osf
Chipped
Multiple Chips



4: Wheel osf
Scratched
Up To 50mm



5: Door osf
Dented
Over 30mm



6: Qtr Panel osr
Dented
With Paint Damage



7: Wheel osr
Scratched
Over 50mm



8: Bumper Rear
Poor Previous Repair
Poor Paint



9: Boot Lid
Chipped
1 To 5



10: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



11: Wheel nsr
Scratched
Over 50mm



12: Door nsf
Dented
With Paint Damage



13: Wing nsf
Scratched
Over 25mm Not Thru Paint



14: Wheel nsf
Scratched
Over 50mm



15: Screen Front
Cracked
Replace

Interior

Carpet Condition -
Seat Condition -

Upholstery Condition -
Odour -

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	Fault
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK