



# VEHICLE INSPECTION REPORT

**CK67XMB**

## BMW X5 xDrive M50d 5dr Auto [7 Seat]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



### Details

Reg. date	28/11/2017	VIN	WBAKS820800Y33136	CAP Average	£20,650.00
Year	2017	Body Style	Estate	CAP Below	£19,250.00
Mileage	69,497 Miles Warranted	Keys	2	Gearbox	AUTOMATIC
Fuel Type	Diesel	MOT Due	15/06/2025	Gears	8
Colour	SILVER	CAP Clean	£22,050.00		

£65 ADDITIONAL FEE

### Tyres



NSF	DUNLOP	6.0mm
NSR	DUNLOP	2.4mm
OSF	DUNLOP	3.0mm
OSR	DUNLOP	2.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Cruise control
- Park assist camera
- Telephone
- Electric sunroof
- Electrically adjustable passenger seat
- Front parking sensor
- PAS
- Radio/CD
- Air conditioning
- Front armrest
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front electric windows
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Rear headrests
- ESP
- Central locking
- Metallic Paint
- Passenger airbag
- Remote central locking
- ABS
- Traction control
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Door Mirror Assy osf  
Scratched (Painted)  
UpTo 25mm Not Thru Paint



2: Door osf  
Chipped  
Edge Chip





3: Door osf  
Dented  
Over 2 UpTo 10mm



4: Bumper Rear  
Chipped  
1 To 5



5: Door Mirror Assy nsf  
Broken  
Replace



6: Wheel nsf  
Scratched  
Up To 50mm



7: Other  
N/A  
N/A



8: Bumper Front  
Scratched  
25 to 100mm Thru Paint



9: Other  
N/A  
N/A



10: Bonnet  
Chipped  
1 To 5



11: Screen Front  
Chipped  
UpTo 10mm

**Interior**

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No

**Vehicle Inspection Report**

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		