



VEHICLE INSPECTION REPORT

VX17MVE

Mercedes-Benz C Class C250d AMG Line 2dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	06/03/2017	Colour	BLACK	MOT Due	19/05/2026
Year	2017	VIN	WDD2054082F523482	Gearbox	Automatic
Mileage	55,721 Miles Warranted	Body Style	Convertible		
Fuel Type	Diesel	Keys	2		

Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	4.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable drivers seat
- Cruise control
- Park assist camera
- Telephone
- Electric sunroof
- Electrically adjustable passenger seat
- Front parking sensor
- PAS
- Radio/CD
- Air conditioning
- Front armrest
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front electric windows
- Rear headrests
- ESP
- Central locking
- Metallic Paint
- Passenger airbag
- Remote central locking
- ABS
- Traction control
- Leather seat trim
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Door nsf
Poor Previous Repair
Poor Colour



2: Door osf
Dented
2 Or Less UpTo 10mm



3: Qtr Panel osr
Chipped
1 To 5




4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Bonnet
Chipped
1 To 5



6: Wheel nsf
Scratched
Over 50mm



7: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		