



VEHICLE INSPECTION REPORT

LJ67UYS

Mercedes-Benz A Class A180 AMG Line Premium Plus 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
2

Details

Reg. date	28/09/2017	Colour	GREY	MOT Due	30/09/2025
Year	2017	VIN	WDD1760422J691941	Gearbox	Automatic
Mileage	82,867 Miles Warranted	Body Style	Hatchback	Doors	5
Fuel Type	Petrol	Keys	2		


Tyres


NSF	MICHELIN	Damaged
NSR	MICHELIN	5.0mm
OSF	MICHELIN	4.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Cruise control
- Park assist camera
- Telephone
- Electric sunroof
- Electrically adjustable passenger seat
- Front parking sensor
- PAS
- Radio/CD
- Air conditioning
- Front armrest
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front electric windows
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Leather seat trim
- Rear headrests
- ESP
- Central locking
- Alloy wheels
- Metallic Paint
- Passenger airbag
- Remote central locking
- ABS
- Traction control
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Up To 50mm



2: Door osf
Chipped
Edge Chip



3: Wheel osr
Scratched
Over 50mm



4: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



5: Door nsr
Scratched
Over 25mm Not Thru Paint



6: Wheel nsr
Scratched
Over 50mm



7: Wheel nsf
Scratched
Up To 50mm



8: Screen Front
Chipped
UpTo 10mm

No Image

No Image

9: Tyre nsf
Damaged
Replace

10: Tyre nsf
Damaged
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		