



VEHICLE INSPECTION REPORT

HR21BUP

MG Mg 5 EXCLUSIVE

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date	11/08/2021	Body Style	Estate	Last service miles	27,500
Year	2021	Keys	2	MOT Due	10/08/2026
Mileage	30,100 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Electric	Service documents	Printout	Gears	1
Colour	RED	Number of stamps	4		
VIN	LSJE24098LG124551	Last service date	21/07/2025		

£100 ADDITIONAL FEE. Last Service - 21.07.2025 at 27500 miles (4 services) Type 3 charging cable

Tyres

NSF	MAXXIS	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	MAXXIS	5.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check




Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Dented
With Paint Damage



4: Door nsf
Dented
With Paint Damage



5: Wheel nsf
Scratched
Over 50mm



6: Door nsr
Chipped
1 To 5



7: Wheel nsr
Scratched
Over 50mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint



10: Wheel osf
Scratched
Up To 50mm



11: Wing osf
Scratched
Up To 25mm Thru Paint



12: Tailgate Trim Panel
Broken
Replace



13: Tailgate
Dented
Over 30mm



14: Lamp osr
Broken
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK