



VEHICLE INSPECTION REPORT

LV21FOP

Nissan Qashqai 1.3 DiG-T 160 [157] Acenta Premium 5dr DCT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	16/03/2021	Body Style	Hatchback	Last service miles	27,716
Year	2021	Keys	2	MOT Due	15/03/2026
Mileage	31,463 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Service Book	Gears	7
Colour	WHITE	Number of stamps	3	Doors	5
VIN	SJNFFAJ11U2914427	Last service date	06/03/2025		

Last service 06/03/2025 at 27,716 miles- 3 services

Tyres

NSF	YOKOHAMA	5.0mm
NSR	YOKOHAMA	5.0mm
OSF	AVON	5.0mm
OSR	CONTINENTAL	Damaged
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Chipped
1 To 5



4: Door nsf
Dented
Over 30mm



5: Door nsr
Chipped
Edge Chip



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



8: Door osr
Dented
Over 30mm



9: Door osf
Poor Previous Repair
Rippled UpTo 30%




10: Wing osf
Poor Previous Repair
Rippled UpTo 30%



11: Roof
Dented
Over 30mm



12: Tyre osr
Damaged
Replace



13: Fascia Trim
Missing
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK