



# VEHICLE INSPECTION REPORT

**GD68MVE**

## Skoda Octavia 1.0 TSI SE Technology 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



### Details

Reg. date	22/01/2019	VIN	TMBKP7NE0K0099990	CAP Average	£5,650.00
Year	2019	Body Style	Estate	CAP Below	£4,800.00
Mileage	77,564 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	21/01/2026	Gears	6
Colour	GREY	CAP Clean	£6,550.00		

£65 ADDITIONAL FEE

Tyres		
NSF	BUDGET	4.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	5.0mm
Spare	BUDGET	OK

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Traction control
- Cloth seat trim
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- PAS
- Radio/CD
- Climate control
- Rear headrests
- ESP
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Qtr Panel osr  
Chipped  
1 To 5



2: Bumper Rear  
Chipped  
1 To 5





3: Qtr Panel nsr  
Dented  
2 Or Less UpTo 10mm



4: Door nsf  
Scratched  
Over 25mm Not Thru Paint



5: Bumper Front  
Chipped  
Multiple Chips



6: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



7: Screen Front  
Chipped  
UpTo 10mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK