



VEHICLE INSPECTION REPORT

LL19FWG

Toyota Prius 1.8 VVTi Business Edition 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	VAT Qualifying
		V5	Present



Details

Reg. date	03/04/2019	Body Style	Hatchback	Last service miles	40,923
Year	2019	Keys	2	MOT Due	02/04/2026
Mileage	46,625 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Hybrid Electric	Service documents	Service Book	Gears	1
Colour	RED	Number of stamps	6	Doors	5
VIN	JTDKB3FU403084076	Last service date	12/05/2025		

Last Service - 12.05.2025 at 40923 miles (6 services)

Tyres

NSF	FALKEN	6.0mm
NSR	DUNLOP	5.0mm
OSF	FALKEN	6.0mm
OSR	DUNLOP	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Steel wheels
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check




Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Dented
With Paint Damage



3: Wing nsf
Chipped
1 To 5



4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint




5: Door nsf
Dented
Over 30mm



6: Door nsr
Chipped
1 To 5



7: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image



9: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

10: Door osr
Dented
Over 2 UpTo 10mm



11: Door osf
Scratched
UpTo 25mm Thru Paint



12: Wing osf
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK