



46 Brampton Road  
Eastbourne  
BN229BN

01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**GX13XTT**

## Kia Ceed 1.4 2 5dr

### Inspection

Serious Damage? No

### Vehicle

VAT Margin

V5 TBC

nama  
GRADE  
3

### Details

Reg. date 28/03/2013

Year 2013

Mileage 85,662 Miles  
Warranted

Fuel Type Petrol

Colour WHITE

VIN U5YHN511LDL068920

Body Style Hatchback

Keys 2

MOT Due 14/05/2025

CAP Clean £2,450.00

CAP Average £2,000.00

CAP Below £1,550.00

Gearbox MANUAL

Gears 6

Doors 5

£100 ADDITIONAL FEE Low Clutch

### Tyres

NSF BUDGET 4.0mm

NSR RAPID 5.0mm

OSF BUDGET 5.0mm

OSR HANKOOK 4.0mm

Spare BUDGET OK

## Features


- Cruise control
- Telephone
- Air conditioning
- Rear headrests
- ESP
- Central locking
- PAS
- Radio/CD
- Front armrest
- Solid Paint
- Rear airbags
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Wing osf  
Chipped  
1 To 5



2: Door osr  
Dented  
Between 10mm + 30mm



3: Door osr  
Chipped  
1 To 5



4: Bumper Rear  
Scratched  
25 to 100mm Thru Paint




5: Bumper Rear  
Chipped  
1 To 5



6: Qtr Panel nsr  
Dented  
Over 30mm



7: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



8: Bonnet  
Chipped  
1 To 5





9: Screen Front  
Chipped  
UpTo 10mm



10: Roof  
Poor Previous Repair  
Paint Flake



11: Wheel osf  
Scratched  
Over 50mm



12: Wheel osr  
Scratched  
Over 50mm



13: Wheel nsr  
Scratched  
Up To 50mm



14: Wheel nsf  
Scratched  
Over 50mm



15: Bumper Front  
Scratched  
25 to 100mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK