



VEHICLE INSPECTION REPORT

RF68DZW

Alfa Romeo Stelvio 2.2 D 190 Super 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	04/12/2018	VIN	ZARPAHGX8K7C42597	Number of stamps	5
Year	2018	Body Style	Estate	Last service date	21/11/2024
Mileage	78,980 Miles Warranted	Keys	2	MOT Due	08/05/2026
Fuel Type	Diesel	Service history	Yes	Gearbox	AUTOMATIC
Colour	GREY	Service documents	Service Book	Gears	8

Last service 21/11/2024, mileage not recorded
Mileage of service before on 11/11/23 was 67,836

Tyres

NSF	MICHELIN	6.0mm
NSR	MICHELIN	6.0mm
OSF	MICHELIN	6.0mm
OSR	MICHELIN	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking

Photos





Condition Check



Damage Photos



1: Bumper Front
Cracked
UpTo 25mm



2: Wing nsf
Dented
Over 30mm



3: Door nsf
Chipped
1 To 5



4: Door nsr
Chipped
1 To 5



5: Wheel nsr
Scratched
Over 50mm



6: Bumper Rear
Poor Previous Repair
Poor Colour



7: Tailgate
Scratched
UpTo 25mm Thru Paint



8: Wheel osr
Scratched
Up To 50mm



9: Door osr
Scratched
UpTo 25mm Thru Paint




10: Door osf
Chipped
Edge Chip



11: Wheel osf
Scratched
Up To 50mm



12: Screen Front
Chipped
UpTo 10mm



13: Wing osf
Scratched
Over 25mm Not Thru Paint



14: Qtr Panel osr
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK