



# VEHICLE INSPECTION REPORT

**AD09JPF**

## Volkswagen Polo 1.2 Match 60 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama  
GRADE  
**3**

### Details

Reg. date	17/06/2009	VIN	WVWZZZ9NZ9Y233608	CAP Average	£580.00
Year	2009	Body Style	Hatchback	CAP Below	£275.00
Mileage	84,617 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	11/06/2025	Gears	5
Colour	SILVER	CAP Clean	£970.00	Doors	5

£65 ADDITIONAL FEE.

### Tyres

NSF	BUDGET	4.0mm
NSR	KUMHO	6.0mm
OSF	FIRESTONE	4.0mm
OSR	AVON	6.0mm
Spare	BUDGET	OK

## Features


- PAS
- Electric door mirrors
- Rear headrests
- ESP
- Alloy wheels
- Rear wiper
- Air conditioning
- Metallic Paint
- Passenger airbag
- Radio/CD
- Climate control
- ABS
- Central locking
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Wing osf  
Dented  
Over 2 UpTo 10mm





3: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint



4: Door osr  
Scratched  
Over 25mm Not Thru Paint



5: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



6: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



7: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



8: Tailgate  
Dented  
Between 10mm + 30mm



9: Door nsr  
Scratched  
Over 25mm Not Thru Paint



10: Bumper Front  
Scratched  
Over 100mm Thru Paint



11: Bonnet  
Scratched  
Over 25mm Thru Paint



12: A Post os  
Chipped  
1 To 5



13: Wheel osr  
Scratched  
Over 50mm



14: Wheel nsr  
Scratched  
Over 50mm





15: Wheel nsf  
Scratched  
Over 50mm



16: Other  
N/A  
N/A

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK