

VEHICLE INSPECTION REPORT

SD70HWP

Vauxhall Corsa 1.2 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	28/09/2020	Colour	WHITE	MOT Due	27/09/2025
Year	2020	VIN	VXKUPHMHDL4363591	Gearbox	MANUAL
Mileage	60,291 Miles Warranted	Body Style	Hatchback	Gears	5
Fuel Type	Petrol	Keys	2	Doors	5

£65 ADDITIONAL FEE.

Tyres

NSF	BUDGET	2.0mm
NSR	NEXEN	4.0mm
OSF	BUDGET	Worn
OSR	MICHELIN	2.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Audio remote control
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Auxiliary input socket
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Telephone
- Digital radio
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Rear parking sensor
- Trip computer
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bumper Rear
Scratched
25 to 100mm Thru Paint



2: Boot Lid
Scratched
Over 25mm Not Thru Paint



3: Wheel osr
Scratched
Up To 50mm




4: Door osr
Dented
Over 2 UpTo 10mm



5: Door osf
Dented
Over 2 UpTo 10mm



6: Wheel osf
Scratched
Up To 50mm



7: Bonnet
Chipped
Multiple Chips




8: Bumper Front
Chipped
Multiple Chips



9: Wheel nsf
Scratched
Up To 50mm




10: Door nsf
Chipped
1 To 5



11: Door nsr
Scratched
Over 25mm Not Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Tyre osf
Worn
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK