



VEHICLE INSPECTION REPORT

GU19DVK

Toyota Aygo 1.0 VVT-i X-Play 5dr x-shift

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	09/03/2019	Body Style	Hatchback	MOT Due	16/03/2026
Year	2019	Keys	2	Gearbox	CVT
Mileage	44,194 Miles Warranted	Service history	Yes	Gears	5
Fuel Type	Petrol	Service documents	Printout	Doors	5
Colour	RED	Number of stamps	1		
VIN	JTDKGNCE50N430968	Last service date	01/11/2024		

£65 ADDITIONAL FEE

Last service 01/11/2024, garage does not record mileage- 1 service

Tyres


NSF	SUNNY	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	SUNNY	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Rear airbags
- Cloth seat trim
- Park assist camera
- Digital radio
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- ESP
- Side airbags
- Steel wheels
- PAS
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Isofix child seat anchor points
- Central locking
- Rear wiper
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint




5: Door nsf
Dented
Over 2 UpTo 10mm




6: Door nsf
Chipped
1 To 5



7: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Door osr
Scratched
Over 25mm Thru Paint

10: Door osf
Dented
Between 10mm + 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK