



VEHICLE INSPECTION REPORT

GU15EFL

Toyota Rav 4 2.0 D-4D Business Edition 5dr 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details


Reg. date	02/03/2015	Body Style	Estate	Last service miles	39,116
Year	2015	Keys	3	MOT Due	01/03/2026
Mileage	102,706 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	5		
VIN	JTMWHREV90D031428	Last service date	22/07/2019		

Last Service - 22.07.2019 at 39116 miles (5 main dealer services) Engine tapping

Tyres


NSF
NSR
OSF
OSR
Spare

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Dented
Over 2 UpTo 10mm

No Image

6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint




8: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm




9: Door nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Up To 50mm




11: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



12: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Scratched
UpTo 25mm Thru Paint



14: Bumper Rear
Scratched
Over 25mm Not Thru Paint



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint




16: Wheel osr
Scratched
Up To 50mm



17: Door osr
Dented
With Paint Damage



18: Door osf
Chipped
1 To 5



19: Door osf
Scratched
Over 25mm Not Thru Paint



20: Wing osf
Chipped
1 To 5



21: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK