



## VEHICLE INSPECTION REPORT

**KO68JWK**

### Citroen Grand C4 Spacetourer 1.2 PureTech 130 Touch Edition 5dr

#### Inspection

Serious Damage? No

#### Vehicle

VAT Margin

V5 Present

nama  
GRADE  
3

#### Details

|           |                            |                  |                  |                    |            |
|-----------|----------------------------|------------------|------------------|--------------------|------------|
| Reg. date | 20/12/2018                 | VIN              | VF73AHNSPJ865834 | Last service date  | 13/02/2020 |
| Year      | 2018                       | Body Style       | MPV              | Last service miles | 27,876     |
| Mileage   | 103,438 Miles<br>Warranted | Keys             | 1                | MOT Due            | 31/07/2026 |
| Fuel Type | Petrol                     | Service history  | Yes              | Gearbox            | MANUAL     |
| Colour    | BEIGE                      | Number of stamps | 1                | Gears              | 5          |

£100 ADDITIONAL FEE.

Service confirmed by Stellantis. Last service 13/02/2020 at 27876 miles (1 main dealer).

#### Tyres

|       |         |       |
|-------|---------|-------|
| NSF   | FARROAD | 6.0mm |
| NSR   | FARROAD | 6.0mm |
| OSF   | FARROAD | 6.0mm |
| OSR   | FARROAD | 6.0mm |
| Spare |         |       |

## Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Passenger airbag
- Cloth seat trim
- Cruise control
- Service indicator
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- ESP
- Central locking
- Rear parking sensor
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Isofix child seat anchor points
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bumper Front  
Scratched  
25 to 100mm Thru Paint



2: Wheel nsf  
Scratched  
Over 50mm



3: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



4: Door nsf  
Dented  
Between 10mm + 30mm



5: Door nsr  
Dented  
Between 10mm + 30mm



6: Qtr Panel nsr  
Dented  
Over 30mm



7: Wheel nsr  
Scratched  
Over 50mm



8: Bumper Rear  
Scratched  
Up To 25mm Thru Paint



9: Wheel osr  
Scratched  
Over 50mm

10: Qtr Panel osr  
Dented  
Between 10mm + 30mm



11: Door osr  
Dented  
Over 30mm

12: Wing osf  
Scratched  
UpTo 25mm Thru Paint

## Interior

Carpet Condition      Average  
Seat Condition      Average

Upholstery Condition      Average  
Odour      No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|               |    |                                                |    |
|---------------|----|------------------------------------------------|----|
| Engine Runs   | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes        | OK | Clutch Slip Test from Static                   | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
|               |    | No Excessive Smoking                           | OK |

|                          |    |                                     |       |
|--------------------------|----|-------------------------------------|-------|
| EML light illuminated    | OK | Oil warning light illuminated       | OK    |
| Airbag light illuminated | OK | Service indicator light illuminated | Fault |
| ABS light illuminated    | OK |                                     |       |
| Windows                  | OK | Radio                               | OK    |
|                          |    | Steering                            | OK    |