



VEHICLE INSPECTION REPORT

LF24A00

Renault Clio 1.6 E-TECH full hybrid 145 Esprit Alpine 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	22/03/2024	Colour	RED	Service history	None
Year	2024	VIN	VF1RJA00472340811	Gearbox	AUTOMATIC
Mileage	7,156 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	Hybrid Electric	Keys	2	Doors	5

£100 ADDITIONAL FEE. Vehicle hasn't had first MOT.

Tyres

NSF	CONTINENTAL	4.0mm
NSR	CONTINENTAL	4.0mm
OSF	CONTINENTAL	3.0mm
OSR	CONTINENTAL	3.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Partial leather seat trim
- Cruise control
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Chipped
Multiple Chips



10: Wheel osr
Scratched
Over 50mm



11: Door osr
Dented
2 Or Less UpTo 10mm



12: Door osf
Dented
2 Or Less UpTo 10mm



13: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK