



VEHICLE INSPECTION REPORT

LG68UZV

Toyota Prius+ 1.8 VVTi Icon TSS 5dr CVT Auto

Inspection

Serious Damage? No

Vehicle

VAT Margin
V5 Buyer To Apply

nama
GRADE
5

Details

Reg. date	01/11/2018	Body Style	MPV	Last service miles	75,175
Year	2018	Keys	2	MOT Due	27/02/2026
Mileage	77,102 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Hybrid Electric	Service documents	Electronic / Online	Gears	1
Colour	GREY	Number of stamps	1		
VIN	JTDZS3EU50J032757	Last service date	28/02/2025		

£100 ADDITIONAL FEE.

Part V5- No green slip

Last service 28/02/2025 at 75,175 miles- 1 service confirmed by Currie Motors Toyota Kingston

Tyres

NSF	CONTINENTAL	2.0mm
NSR	MICHELIN	4.0mm
OSF	FALKEN	2.0mm
OSR	MICHELIN	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Cracked
Over 25mm



3: Wing osf
Dented
Over 30% Of Panel



4: Door osf
Dented
Over 30mm



5: Door osr
Scratched
Over 25mm Thru Paint



6: Qtr Panel osr
Dented
With Paint Damage



7: Bumper Rear
Scratched
Over 100mm Thru Paint



8: Boot Lid
Dented
Between 10mm + 30mm



9: Qtr Panel nsr
Dented
Over 30mm



10: Door nsr
Dented
Over 30mm



11: Door nsf
Dented
Over 30mm



12: Wing nsf
Dented
With Paint Damage



13: Carpets Front
Torn
Over 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK