



VEHICLE INSPECTION REPORT

OY67RHO

Ford Kuga 1.5 EcoBoost 120 Zetec 5dr 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	26/09/2017	Body Style	Hatchback	Last service miles	64,394
Year	2017	Keys	2	MOT Due	04/10/2026
Mileage	75,950 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	SILVER	Number of stamps	3	Doors	5
VIN	WF0AXXWPMAC83384	Last service date	01/10/2024		

£100 ADDITIONAL FEE.

LAST SERVICE 1/10/24 @ 64,394 MILES (3 SERVICES 2 MAIN DEALER) PRINT Blade missing from one of the key
Smoking

Tyres

NSF	GOODYEAR	5.0mm
NSR	GOODYEAR	5.0mm
OSF	GOODYEAR	5.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wing nsf
Poor Previous Repair
Poor Paint



5: Door nsf
Poor Previous Repair
Poor Paint



6: Door nsr
Dented
Over 30mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Bumper Rear
Scratched
Up To 25mm Thru Paint



9: Qtr Panel osr
Poor Previous Repair
Poor Paint



10: Door osr
Chipped
1 To 5



11: Door osf
Chipped
Edge Chip



12: Wing osf
Chipped
1 To 5



13: Roof
Chipped
Edge Chip



14: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	Fault
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK