



VEHICLE INSPECTION REPORT

YD72HJZ

Kia Xceed 1.5T GDi ISG 4 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	09/09/2022	VIN	U5YH5F15LNL124013	Gearbox	MANUAL
Year	2022	Body Style	Hatchback	Gears	6
Mileage	30,743 Miles Warranted	Keys	2	Doors	5
Fuel Type	Petrol	Service history	None		
Colour	RED	MOT Due	24/09/2026		

No service history

Tyres

NSF	MAXXIS	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	MAXXIS	5.0mm
OSR	SUNNY	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric sunroof
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking

Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Scratched
Up To 50mm



4: Door nsf
Scratched
UpTo 25mm Thru Paint



5: Wheel nsr
Scratched
Up To 50mm



6: Qtr Panel osr
Chipped
1 To 5



7: Wheel osr
Scratched
Over 50mm



8: Door osr
Chipped
Edge Chip



9: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		