



VEHICLE INSPECTION REPORT

DP69UXJ

Nissan Qashqai 1.3 DiG-T N-Connecta 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
3

Details

Reg. date 31/01/2020

VIN SJNFFAJ11U2753651

Gearbox MANUAL

Year 2020

Body Style Hatchback

Gears 6

Mileage 43,495 Miles
Warranted

Keys 1

Doors 5

Fuel Type Petrol

Service history None

Colour BLACK

MOT Due 30/01/2026

No service history

Tyres

NSF BUDGET 5.0mm

NSR BUDGET 6.0mm

OSF BUDGET 5.0mm

OSR ACCELERA 5.0mm

Spare

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wing nsf
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm



5: Door osf
Chipped
Edge Chip



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Tailgate
Scratched
UpTo 25mm Thru Paint



8: Wheel osr
Corroded
Light



9: Door osr
Chipped
Edge Chip



10: Door osf
Chipped
Edge Chip



11: Wing osf
Scratched
UpTo 25mm Thru Paint



12: Wheel osf
Scratched
Over 50mm



13: Screen Front
Chipped
UpTo 10mm



14: Bumper Rear
Scratched
25 to 100mm Thru Paint

Interior

Carpet Condition -
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK