



VEHICLE INSPECTION REPORT

ME21PUA

Ford Ranger Pick Up Double Cab Wildtrak 2.0 EcoBlue 213 Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Photocopy



Details

Reg. date	27/08/2021	Colour	SILVER	MOT Due	26/08/2026
Year	2021	VIN	6FPPXXMJ2PMR18841	Gearbox	AUTOMATIC
Mileage	68,649 Miles Warranted	Body Style	Pick-up	Gears	1
Fuel Type	Diesel	Service history	None	Doors	4

Timing belt replaced 24/09/2025 at 68273 miles.
Photocopy of V5.


Tyres

NSF	YOKOHAMA	7.0mm
NSR	YOKOHAMA	7.0mm
OSF	YOKOHAMA	7.0mm
OSR	YOKOHAMA	7.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Towbar
- Metallic Paint
- Leather seat trim
- Cruise control
- Park assist camera
- Air conditioning
- Drivers airbag
- Front parking sensor
- Rear parking sensor
- Front electric windows
- Passenger airbag
- Heated front seat
- Digital radio
- Rear electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Door nsf
Scratched
Over 25mm Thru Paint



4: Door nsr
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



6: Tailgate
Scratched
UpTo 25mm Thru Paint



7: Door osr
Dented
2 Or Less UpTo 10mm



8: Door osf
Scratched
UpTo 25mm Thru Paint



9: Wing osf
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK