



VEHICLE INSPECTION REPORT

CK19ZVR

Volkswagen Polo 1.0 TSI 95 R-Line 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	14/03/2019	Body Style	Hatchback	Last service miles	35,908
Year	2019	Keys	1	MOT Due	14/03/2026
Mileage	38,272 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	RED	Number of stamps	4	Doors	5
VIN	WVVZZZAWZKU046024	Last service date	11/03/2025		

Last Service - 11.03.2025 at 35908 miles (4 services) Breaks need checking

Tyres

NSF	AVON	3.0mm
NSR	AVON	5.0mm
OSF	AVON	3.0mm
OSR	AVON	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Scratched
Up To 50mm



4: Door nsf
Scratched
UpTo 25mm Thru Paint



5: Wheel nsr
Scratched
Up To 50mm




6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Qtr Panel osr
Poor Previous Repair
Poor Paint



8: Door osr
Scratched
Over 25mm Thru Paint



9: Door osf
Poor Previous Repair
Rippled UpTo 30%



10: Wheel osf
Scratched
Over 50mm



11: Wheel osr
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK