



VEHICLE INSPECTION REPORT

GY15WFO

Audi Q3 2.0 TDI Quattro SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	19/06/2015	Body Style	Estate	Last service miles	76,995
Year	2015	Keys	2	MOT Due	15/06/2026
Mileage	78,264 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	7		
VIN	WAUZZZ8UXGR004391	Last service date	16/06/2025		

£65 ADDITIONAL FEE

Last service 16/06/2025 at 76,995 miles- 7 main dealer services


Tyres

NSF	HANKOOK	4.0mm
NSR	BUDGET	3.0mm
OSF	HANKOOK	2.0mm
OSR	RAPID	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Central locking
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Remote central locking
- Rear parking sensor
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Over 5mm



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front Moulding
Broken
Replace



4: Wing nsf
Dented
With Paint Damage



5: Wheel nsf
Scratched
Up To 50mm



6: Door nsf
Poor Previous Repair
Poor Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Up To 50mm



9: Qtr Panel nsr
Chipped
1 To 5



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Boot Lid
Dented
2 Or Less UpTo 10mm



12: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



13: Wheel osr
Scratched
Up To 50mm



14: Door osr
Dented
With Paint Damage



15: Door osf
Chipped
Edge Chip

No Image

16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Wing osf
Chipped
1 To 5



18: Wheel osf
Scratched
Over 50mm



19: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK