



VEHICLE INSPECTION REPORT

LV72FPC

Ford Kuga 1.5 EcoBoost 150 ST-Line X Edition 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	03/09/2022	Body Style	Hatchback	Last service miles	35,554
Year	2022	Keys	2	MOT Due	02/09/2026
Mileage	37,143 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	2	Doors	5
VIN	WF0FXXWPMFNM86272	Last service date	29/08/2025		

£65 ADDITIONAL FEE

Last service 29/08/2025 at 35,554 miles- 2 services (1 main dealer)

Tyres


NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Up To 50mm



4: Door nsf
Chipped
Edge Chip



5: Door nsr
Scratched
Over 25mm Thru Paint



6: Door osr
Dented
2 Or Less UpTo 10mm



7: Door osf
Scratched
UpTo 25mm Thru Paint



8: Wing osf
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		