



VEHICLE INSPECTION REPORT

AO05TXD

Nissan X-Trail 2.2 dCi 136 Sport 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	02/07/2005	Body Style	Estate	Last service miles	95,543
Year	2005	Keys	2	MOT Due	Expired
Mileage	97,606 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	20		
VIN	JN1TENT30U0214650	Last service date	20/06/2024		

Last Service: 20/06/2024 at 95543 miles. (20 main dealer services) Front bumper insecure

Tyres


NSF	DAVANTI	4.0mm
NSR	DUNLOP	3.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- PAS
- Audio remote control
- Electric sunroof
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Rear parking sensor
- Radio/CD
- Opening panoramic glass roof
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Rear electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Bumper Front
Cracked
Over 25mm



2: Bonnet
Chipped
1 To 5



3: Wing nsf
Scratched
Over 25mm Not Thru Paint



4: Wheel nsf
Corroded
Light




5: Door nsf
Chipped
Multiple Chips



6: Door nsr
Chipped
1 To 5




7: Wheel nsr
Scratched
Up To 50mm



8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Boot Lid
Scratched
Over 25mm Not Thru Paint



11: Wheel osr
Scratched
Up To 50mm



12: Door osr
Chipped
1 To 5



13: Door osf
Poor Previous Repair
Poor Paint



14: Wing osf
Scratched
Over 25mm Not Thru Paint



15: Wheel osf
Scratched
Up To 50mm



16: Roof
Rusted
Over 5mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK