

# VEHICLE INSPECTION REPORT

**OW17FOP**

## Land Rover Discovery Sport 2.0 TD4 180 SE Tech 5dr Auto

| Inspection      |    | Vehicle |        |
|-----------------|----|---------|--------|
| Serious Damage? | No | VAT     | Margin |
|                 |    | V5      | TBC    |



### Details

|           |                           |            |                   |         |            |
|-----------|---------------------------|------------|-------------------|---------|------------|
| Reg. date | 20/06/2017                | Colour     | GREY              | MOT Due | 01/10/2026 |
| Year      | 2017                      | VIN        | SALCA2AN8HH711984 | Gearbox | AUTOMATIC  |
| Mileage   | 80,846 Miles<br>Warranted | Body Style | Estate            | Gears   | 9          |
| Fuel Type | Diesel                    | Keys       | 2                 |         |            |

### Tyres

|       |         |       |
|-------|---------|-------|
| NSF   | PIRELLI | 3.0mm |
| NSR   | PIRELLI | 4.0mm |
| OSF   | PIRELLI | 3.0mm |
| OSR   | PIRELLI | 4.0mm |
| Spare |         |       |

## Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bumper Rear  
Scratched  
Over 100mm Thru Paint



2: Boot Lid  
Dented  
Over 2 UpTo 10mm



No Image

No Image


3: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint

4: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



5: Wheel osr  
Scratched  
Over 50mm

6: Door osr  
Chipped  
Multiple Chips



7: Door osf  
Chipped  
1 To 5

8: Door osf  
Scratched  
Over 25mm Not Thru Paint

No Image



9: Wing osf  
Scratched  
Over 25mm Not Thru Paint

10: Wheel osf  
Scratched  
Up To 50mm



11: Bonnet  
Chipped  
Multiple Chips



12: Bumper Front  
Scratched  
25 to 100mm Thru Paint

No Image



13: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

14: Wing nsf  
Dented  
Over 2 UpTo 10mm



No Image



15: Wing nsf  
Scratched  
Over 25mm Not Thru Paint

16: Wheel nsf  
Scratched  
Up To 50mm



17: Door nsf  
Chipped  
Multiple Chips



18: Door nsr  
Chipped  
Multiple Chips



19: Wheel nsr  
Scratched  
Over 50mm

No Image

20: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



21: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm

## Interior

Carpet Condition  
Seat Condition

Average  
Average

Upholstery Condition  
Odour

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|                          |    |                                                |    |
|--------------------------|----|------------------------------------------------|----|
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Turbo Boosting           | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake            | OK | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | DPF light illuminated                          | OK |
| ABS light illuminated    | OK | Service indicator light illuminated            | OK |
| Windows                  | OK | Radio                                          | OK |
| Sat nav                  | OK | Steering                                       | OK |