



VEHICLE INSPECTION REPORT

FH72DAA

Ford Fiesta 1.0 EcoBoost Hybrid mHEV 125 Titanium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	08/02/2023	VIN	WF0JXXGAHJNB71759	Last service date	20/06/2025
Year	2023	Body Style	Hatchback	Last service miles	53,001
Mileage	61,431 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	SILVER	Number of stamps	5	Doors	5

£65 ADDITIONAL FEE

Last service 20/06/2025 at 53,001 miles- 5 services (3 main dealer) Handbrake fault

Tyres



NSF	FALKEN	5.0mm
NSR	NEXEN	5.0mm
OSF	FALKEN	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- PAS
- Digital radio
- Full size spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wing nsf
Chipped
1 To 5




4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Chipped
1 To 5



6: Door nsr
Scratched
UpTo 25mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



8: Door osr
Scratched
UpTo 25mm Thru Paint



9: Door osf
Chipped
1 To 5



10: Wheel osf
Scratched
Up To 50mm



11: Roof
Chipped
Edge Chip



12: Carpets Front
Holed
Over 3mm



13: Bumper Front
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	Fault	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK