



# VEHICLE INSPECTION REPORT

**FN65JOH**

## Toyota Yaris 1.33 VVT-i Icon 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	01/09/2015	Service history	Yes	CAP Average	£5,350.00
Year	2015	Service documents	Service Book	CAP Below	£4,500.00
Mileage	31,673 Miles Warranted	Number of stamps	5	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	26/08/2021	Gears	6
Colour	BLUE	Last service miles	22,533	Doors	5
VIN	VNKKJ3D3X0A305101	MOT Due	26/07/2025		
Body Style	Hatchback	CAP Clean	£6,175.00		

Last Service - 26.08.2021 at 57744 miles (5 main dealer services)

### Tyres



NSF	DUNLOP	4.0mm
NSR		4.0mm
OSF	DUNLOP	5.0mm
OSR	RAPID	5.0mm
Spare		

## Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Traction control
- Alloy wheels
- PAS
- Body coloured bumpers
- Climate control
- Rear headrests
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Trip computer
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wing nsf  
Dented  
With Paint Damage



4: Wheel nsf  
Scratched  
Over 50mm




5: Door nsf  
Dented  
Between 10mm + 30mm



6: Door nsr  
Scratched  
Over 25mm Not Thru Paint




7: Bumper Rear  
Poor Previous Repair  
Poor Colour




8: Boot Lid  
Dented  
Over 30mm



9: Wheel nsr  
Scratched  
Over 50mm



10: Door osr  
Scratched  
Over 25mm Not Thru Paint



11: Door osf  
Scratched  
Over 25mm Not Thru Paint



12: Wheel osf  
Scratched  
Over 50mm

**Interior**

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

**Vehicle Inspection Report**

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK