



VEHICLE INSPECTION REPORT

KP13OCD

Skoda Rapid 1.2 TSI S 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	26/03/2013	Body Style	Hatchback	Last service miles	76,936
Year	2013	Keys	1	MOT Due	30/03/2026
Mileage	133,672 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	5	Doors	5
VIN	TMBBM6NH5D4019849	Last service date	11/07/2019		

LAST SERVICE 11/7/19 @ 76,936 MILES (5 SERVICES 2 MAIN DEALER) BOOK AND PRINT



Tyres

NSF	RAPID	4.0mm
NSR	RAPID	4.0mm
OSF	DUNLOP	4.0mm
OSR	RAPID	4.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Height adjustable drivers seat
- ABS
- Side airbags
- Cloth seat trim
- Rear wiper
- Climate control
- Rear headrests
- Drivers airbag
- Traction control
- Steel wheels
- Radio/CD
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Body coloured bumpers
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
Over 100mm Thru Paint



2: Qtr Panel or
Chipped
Multiple Chips



3: Door osr
Chipped
Multiple Chips



4: Door osf
Poor Previous Repair
Poor Paint



5: Wing osf
Chipped
Multiple Chips



6: Bonnet
Dented
With Paint Damage



7: Bumper Front
Scratched
Over 100mm Thru Paint



8: Wing nsf
Chipped
1 To 5

No Image



9: Wing nsf
Scratched
Over 25mm Not Thru Paint

10: Door nsf
Scratched
Over 25mm Thru Paint



11: Door nsr
Scratched
Over 25mm Thru Paint



12: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



13: Sill ns
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK