



VEHICLE INSPECTION REPORT

RF69PRZ

Audi Q2 35 TFSI Black Edition 5dr S Tronic

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 TBC

nama
GRADE
4

Details

Reg. date 15/02/2020

Year 2020

Mileage 30,664 Miles
Warranted

Fuel Type Petrol

Colour BLUE

VIN WAUZZZGA5LA013323

Body Style Estate

Keys 2

MOT Due 14/02/2026

Gearbox SEMI AUTO

Gears 7

Tyres

NSF HANKOOK 3.0mm

NSR HANKOOK 3.0mm

OSF BRIDGESTONE 3.0mm

OSR BUDGET 5.0mm


Spare

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Audio remote control
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Paint Flake



2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Chipped
1 To 5



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Chipped
1 To 5




8: Wheel nsr
Scratched
Up To 50mm



9: Qtr Panel nsr
Chipped
1 To 5



10: Bumper Rear
Chipped
Multiple Chips



11: Bumper Rear
Scratched
Over 25mm Not Thru Paint



12: Boot Lid
Dented
Over 2 UpTo 10mm



13: Qtr Panel osr
Chipped
1 To 5




14: Wheel osr
Scratched
Up To 50mm



15: Door osr
Dented
With Paint Damage



16: Door osf
Scratched
Over 25mm Thru Paint



17: Screen Front
Chipped
UpTo 10mm



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK